

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/14/2020	Time:	9:08 AM
Name of School Corporation:	TAYLOR COMMUNITY SCHOOL CORP.		Corp ID:	343460	
Address of School Corporation:	3750 E CR 300 S				
City:	Kokomo	Zip:	46902	County Number:	34
VIN:	4UZABRFC8KCKR8654	License Number:	22239	Bus Number:	6
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	18820	Year:	2019
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
50-1-3	The seat belt cutter is contained in a compartment.
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
64-2-1	Any rear turn signal does not function properly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.