## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/26/2020 Time: 9:04 AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUAAN78B499582License Number:NB33Bus Number:33Make of Body:IC Corporation Year:2007Make of Chassis:IC Corporation Year:2007

Bus Type: A1 Mileage: 133460

Inspection Status: R Inspected By: Mark Raper PE: 6473

## Violations - Rejected

Inspection Code Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.