## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/26/2020 Time: 9:53 AM Name of School CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300 Corporation: **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1GB6G5BG5B1162740 2625 **Bus Number:** 44 Number: Make of Collins Bus GMC Year: 2011 Make of Body: Year: 2011 Chassis: Corporation **Bus Type:** A2 Mileage: 155018 Inspected PE: **Inspection Status:** 0 6473 Mark Raper By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

## **Violations - Out of Service**

<u>Inspection Code</u>

65-2-1

<u>Description</u>

Warning lights fail to operate correctly

8-2-1 There is no brake certification, or the certification has expired or is not signed

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.