

## REPORT OF SCHOOL BUS INSPECTION

|   |                                     |   |
|---|-------------------------------------|---|
| <b>Type of Inspection:</b> Re-Inspection                        | <b>Date:</b> 5/27/2020              | <b>Time:</b> 8:26 AM                          |
| <b>Name of School Corporation:</b> VINCENNES COMM. SCHOOL CORP. | <b>Corp ID:</b> 424335              |   |
| <b>Address of School Corporation:</b> 1712 S Hart St Rd         |                                     |   |
| <b>City:</b> Vincennes  | <b>Zip:</b> 47591                   | <b>County Number:</b> 42                      |
| <b>VIN:</b> 1BAKFCKH25F227331                                   | <b>License Number:</b> B223D        | <b>Bus Number:</b> 1                          |
| <b>Make of Body:</b> Blue Bird Corporation                      | <b>Year:</b> 2004                   | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Bus Type:</b> C  | <b>Mileage:</b> 85127               | <b>Year:</b> 2005                             |
| <b>Inspection Status:</b> O                                     | <b>Inspected By:</b> Bradley Miller | <b>PE:</b> 7809                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 23-1-3                 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 82-1-2                 | See Notes: Any defect inspector deems a violation not listed  |
| 55-1-6                 | See Notes: Any defect inspector deems a violation not listed  |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**