REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	5/29/2020	Time:	10:37 AM
Name of School Co	orporation:	BLACKFORD COUN	ITY SCHOOLS		Corp ID:	50515
Address of School	Corporation:	668 W CR 200	S			
City:	Hartford City	Zip:	47348		County Number:	5
VIN:	4DRBUAAN4E	DB156707	License Number:	3084	Bus Number:	112
Make of Body:	IC Corporation	Year: 2012	Make of Chassis:	IC Corporation	Year:	2013
Bus Type:	С		Mileage:	101740		
Inspection Status:	0	Inspected By:	Jamie Hotchkiss		PE:	6458

Violations - Rejected

Inspection Code	Description
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.