REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 5/29/2020 Time: 10:37 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number: 5VIN:4DRBUAAN4DB156707License Number: 3084Bus Number: 112

Make of Body: IC Corporation Year: 2012 Make of Chassis: IC Corporation Year: 2013

Bus Type: C Mileage: 101740

Inspection Status: O Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

Any front turn signal does not function properly

Violations - Out of Service

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.