## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	6/16/2020	Time:	9:39 AM
Name of School Co	•	SOU		COMM. SCH. COF	RP	Corp ID:	313190
Address of School	Corporation:		315 S Harrisor	n Dr			
City:	Corydon		Zip:	47112		County Number:	31
VIN:	4DRBBAAP03B5816	71		License Number:	B870D	Bus Number:	38
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	Chevrolet	Year:	2003
Bus Type:	С			Mileage:	123158		
Inspection Status:	0		Inspected By:	Troy Boyd		PE:	5171

## **Violations - Rejected**

Inspection Code	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
35-1-1	A heater motor is not operating properly
68-1-1	Washers do not function properly in any manner

## **Violations - Out of Service**

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.