## REPORT OF SCHOOL BUS INSPECTION

Address of School Corporation: 626 N Huntersville Rd

City:BatesvilleZip:47006County Number:69VIN:4DRBUAAN1CB630840License Number:Bus Number:15Make of Body:IC Corporation Year:2012

Bus Type: C Mileage: 105052

Inspection Status: O Inspected By: Dan Elmore PE: 5960

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

## **Violations - Out of Service**

## <u>Inspection Code</u> <u>Description</u>

53-2-3 Coil springs, torque rods or torsion bars are broken or missing

65-2-1 Warning lights fail to operate correctly

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.