

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|-------------------------|------------------------|------------|-------------------------|-------------------------|--------------|------|
| Type of Inspection: | Annual | Date: | 6/24/2020 | Time: | 10:18 AM | | |
| Name of School Corporation: | MILAN COMMUNITY SCHOOLS | | | Corp ID: | 696910 | | |
| Address of School Corporation: | 412 E Carr St | | | | | | |
| City: | Milan | Zip: | 47031 | County Number: | 69 | | |
| VIN: | 1GB3G2BG9D1165385 | License Number: | 18984 | Bus Number: | A5 | | |
| Make of Body: | Chevrolet | Year: | 2013 | Make of Chassis: | Collins Bus Corporation | Year: | 2013 |
| Bus Type: | A1 | Mileage: | 41828 | | | | |
| Inspection Status: | A | Inspected By: | Dan Elmore | PE: | 5960 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.