

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/23/2020	<b>Time:</b> 9:13 AM
<b>Name of School Corporation:</b> CROTHERSVILLE COMM. SCHOOLS	<b>Corp ID:</b> 363710	
<b>Address of School Corporation:</b> 201 S Preston St		
<b>City:</b> Crothersville	<b>Zip:</b> 47229	<b>County Number:</b> 36
<b>VIN:</b> 4DRAPSKK0DB043219	<b>License Number:</b> 16NEW	<b>Bus Number:</b> 16
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2011	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2011		
<b>Bus Type:</b> C	<b>Mileage:</b> 39799	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Travis Coryea	<b>PE:</b> 5892

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**