

## REPORT OF SCHOOL BUS INSPECTION

|  |                                   |  |
|--|-----------------------------------|--|
| <b>Type of Inspection:</b> Annual                                | <b>Date:</b> 6/3/2020             | <b>Time:</b> 8:28 PM                   |
| <b>Name of School Corporation:</b> ELWOOD COMMUNITY SCHOOL CORP. | <b>Corp ID:</b> 485280            |  |
| <b>Address of School Corporation:</b> 1306 N Anderson St         |                                   |  |
| <b>City:</b> Elwood  | <b>Zip:</b> 46036                 | <b>County Number:</b> 48               |
| <b>VIN:</b> 4DRBUAFP95B979337                                    | <b>License Number:</b> 20375      | <b>Bus Number:</b> 19                  |
| <b>Make of Body:</b> IC Corporation                              | <b>Year:</b> 2004                 | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2004  | <b>Mileage:</b> 96469             | <b>Year:</b> 2004                      |
| <b>Bus Type:</b> B   |                                   |  |
| <b>Inspection Status:</b> A                                      | <b>Inspected By:</b> Jeremy Mason | <b>PE:</b> 8139                        |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.