

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 6/26/2020      **Time:** 10:10 AM  
**Name of School Corporation:** PRIMROSE SCHOOL OF W. FISHERS      **Corp ID:** 290004  
**Address of School Corporation:** 12609 Parkside Dr.  
**City:** Fishers      **Zip:** 46038      **County Number:** 29  
**VIN:** 1GBHG31C681181818      **License Number:** B930AC      **Bus Number:** 2  
**Make of Body:** Chevrolet      **Year:** 2008      **Make of Chassis:** Chevrolet      **Year:** 2008  
**Bus Type:** A1      **Mileage:** 48060  
**Inspection Status:** R      **Inspected By:** Jeff Kastenschmidt      **PE:** 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**