# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 7/6/2020 | **Time:** | 10:18 AM |
| **Name of School Corporation:** | CREME DE LA CREME CARMEL | | | **Corp ID:** | |
| **Address of School Corporation:** | 760 E 116th Street | | | | |
| **City:** | Carmel | **Zip:** | 46032 | **County Number:** | 29 |
| **VIN:** | 1GB0GRBFXG1282688 | **License Number:** | 1A | **Bus Number:** | 1 |
| **Make of Body:** | Chevrolet **Year:** 2016 | **Make of Chassis:** | Starcraft | **Year:** | 2016 |
| **Bus Type:** | A1 | **Mileage:** | 14580 | | |
| **Inspection Status:** | O | **Inspected By:** | Jeff Kastenschmidt | **PE:** | 5805 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 70-1-12 | See Notes: Any defect inspector deems a violation not listed |
| 43-1-8 | Any required lettering is missing or faded. |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 41-2-1 | Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students) |
| 50-2-1 | There is no seat belt cutter in the vehicle |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**