# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 7/7/2020 | **Time:** | 9:26 AM |
| **Name of School Corporation:** | EAST GIBSON SCHOOL CORPORATION | | | **Corp ID:** | 262725 |
| **Address of School Corporation:** | 941 S Franklin St | | | | |
| **City:** | Oakland City | **Zip:** | 47660 | **County Number:** | 26 |
| **VIN:** | 1GB6G3AG8A1165037 | **License Number:** | 2369 | **Bus Number:** | 22 |
| **Make of Body:** | Star Trans **Year:** 2010 | **Make of Chassis:** | Chevrolet | **Year:** | 2010 |
| **Bus Type:** | | **Mileage:** | 101251 | | |
| **Inspection Status:** | A | **Inspected By:** | Bradley MIller | **PE:** | 7809 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type | Description |
|---|---|