REPORT OF SCHOOL BUS INSPECTION

Type of 8:55 Annual Time: Date: 7/10/2020 Inspection: AM Name of School Corporation: CROWN POINT COMM. SCHOOL CORP. Corp ID: 454660 **Address of School Corporation:** 1151 E Summit County City: Crown Point Zip: 46307 45 Number: License VIN: 4UZABRD68ACAR0830 72299 Bus Number: 87 Number: Thomas Built Buses, Year: 2009 Thomas Built Buses, Year: Make of Make of Body: 2010 Chassis: Inc. **Bus Type:** С Mileage: 90764 Inspection Inspected PE: Α Tim Grayson 7558 Status: By:

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.