

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/13/2020	Time:	8:56 AM		
Name of School Corporation:	BAUGO COMMUNITY SCHOOLS			Corp ID:	202260		
Address of School Corporation:	29125 CR 22 W						
City:	Elkhart	Zip:	46517	County Number:	20		
VIN:	4DRNUAAN1EB417308		License Number:	B979N	Bus Number:	7	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	C			Mileage:	49564		
Inspection Status:	R	Inspected By:	Wes Rowlader	PE:	7427		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-3	The seat belt cutter is contained in a compartment.
52-1-2	Any shock absorber is leaking fluid
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.