REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 7/13/2020 Time: 8:56 AM

Name of School Corporation: BAUGO COMMUNITY SCHOOLS

Corp ID: 202260

Address of School Corporation: 29125 CR 22 W

City:ElkhartZip:46517County Number:20VIN:4DRNUAAN1EB417308License Number:B979NBus Number:7Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2014

Bus Type: C Mileage: 49564

Inspection Status: R Inspected By: Wes Rowlader PE: 7427

Violations - Rejected

Inspection Code	<u>Description</u>
50-1-3	The seat belt cutter is contained in a compartment.
52-1-2	Any shock absorber is leaking fluid
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.