## REPORT OF SCHOOL BUS INSPECTION

Type of 9:57 7/14/2020 **Time**: Annual Date: Inspection: AM Name of School Corporation: **BAUGO COMMUNITY SCHOOLS** 202260 Corp ID: **Address of School Corporation:** 29125 CR 22 W County City: Elkhart Zip: 46517 20 Number: License VIN: 1GB3G3BG4D1191284 6785 **Bus Number:** 31 Number: Make of Thomas Built Buses, Chevrolet Year: Year: 2013 Make of Body: 2013 Inc. Chassis: **Bus Type:** A2 Mileage: 89859 Inspected PE: **Inspection Status:** R Wes Rowlader 7427 By:

### **Violations - Rejected**

# Inspection Code

#### **Description**

29-1-2 Floor covering is missing, cut, loose, buckled, bulging, or not secure

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.