REPORT OF SCHOOL BUS INSPECTION

Type of 8:59 Time: Annual Date: 7/16/2020 Inspection: AM Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750 **Address of School Corporation:** 2 S 3rd St. County City: Flora Zip: 46929 8 Number: License VIN: 1BAKECPH4AE271303 72274 Bus Number: Number: Make of Blue Bird Blue Bird Year: 2010 Make of Body: Year: 2010 Corporation Chassis: Corporation **Bus Type:** С Mileage: 101068 Inspection Inspected R PE: 7421 Nate King

Violations - Rejected

Status:

<u>Inspection Code</u> <u>Description</u>

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

By:

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.