## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:7/16/2020Time:9:06 AMName of School Corporation:CARROLL CONS. SCHOOL CORP.Corp ID:80750

Address of School Corporation: 2 S 3rd St.

City:FloraZip:46929County Number:8VIN:4DRBUC8P8JB048377License Number:18858Bus Number:8Make of Body:IC Corporation Year:2017Make of Chassis:IC Corporation Year:2018

Bus Type: C Mileage: 35108

Inspection Status: R Inspected By: Nate King PE: 7421

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.