## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:7/16/2020Time:9:13 AMName of School Corporation:CARROLL CONS. SCHOOL CORP.Corp ID:80750

Address of School Corporation: 2 S 3rd St.

City: Flora Zip: 46929 County Number: 8

VIN: 4DRBUSKP0FB529945 License Number: 7413 Bus Number: 21

Make of Body: IC Corporation Year: 2015 Make of Chassis: IC Corporation Year: 2015

Bus Type: C Mileage: 76657

Inspection Status: R Inspected By: Nate King PE: 7421

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

2-1-4 LED type lights have 25% or more of the pixels inoperable in any one light

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.