

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 7/16/2020	Time: 9:27 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP.		Corp ID: 80750
Address of School Corporation: 2 S 3rd St.		
City: Flora	Zip: 46929	County Number: 8
VIN: 4DRBUAAP3DB198609	License Number: 4508	Bus Number: 3
Make of Body: IC Corporation	Year: 2013	Make of Chassis: IC Corporation
Year: 2013		Year: 2013
Bus Type: C	Mileage: 85176	
Inspection Status: R	Inspected By: Nate King	PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.