REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	7/16/2020	**Time:**	11:47 AM
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.				**Corp ID:**	80750
Address of School Corporation:	2 S 3rd St.					
City:	Flora	**Zip:**	46929		**County Number:**	8
VIN:	1GB3G2BL3E1174467		**License Number:**	26781	**Bus Number:**	5sb
Make of Body:	Starcraft **Year:**	2014	**Make of Chassis:**	Starcraft	**Year:**	2014
Bus Type:			**Mileage:**	67463		
Inspection Status:	R	**Inspected By:**	Nate King		**PE:**	7421

Violations - Rejected

Inspection Code	Description
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description

Bus Type Description