

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 7/16/2020      **Time:** 11:48 AM  
**Name of School Corporation:** CARROLL CONS. SCHOOL CORP.      **Corp ID:** 80750  
**Address of School Corporation:** 2 S 3rd St.  
**City:** Flora      **Zip:** 46929      **County Number:** 8  
**VIN:** 1GB3G2BL3E1174467      **License Number:** 26781      **Bus Number:** 5sb  
**Make of Body:** Starcraft      **Year:** 2014      **Make of Chassis:** Starcraft      **Year:** 2014  
**Bus Type:**      **Mileage:** 67463  
**Inspection Status:** A      **Inspected By:** Nate King      **PE:** 7421

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description