## REPORT OF SCHOOL BUS INSPECTION

Type of 8:45 Annual Time: Date: 7/21/2020 Inspection: AM Name of School Corporation: MIDDLEBURY COMMUNITY SCHOOLS Corp ID: 202275 **Address of School Corporation:** 57853 N Ridge Dr County City: Middlebury Zip: 46540 20 Number: License VIN: 1BAKGCPAX7F241313 30376 Bus Number: Number: Make of Blue Bird Blue Bird Year: 2006 Make of Body: Year: 2007 Corporation Chassis: Corporation **Bus Type:** С Mileage: 122714 Inspection Inspected 0 PE: Wes Rowlader 7427

**Violations - Rejected** 

Status:

**Inspection Code Description** 

**Violations - Out of Service** 

<u>Inspection Code</u> <u>Description</u>

32-2-1 There is fuel leaking from any point on in the fuel system

By:

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.