

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/27/2020	Time:	9:56 AM
Name of School Corporation:	MEDORA COMMUNITY SCHOOL CORP.			Corp ID:	363640
Address of School Corporation:	Box 248				
City:	Medora	Zip:	47260	County Number:	36
VIN:	1BAKFCPA4BF274979	License Number: 4413			Bus Number: 2
Make of Body:	Blue Bird Corporation	Year:	2009	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	86244	Year:	2010
Inspection Status:	R	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.