

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 7/27/2020 **Time:** 9:09 AM
Name of School Corporation: SOUTH DEARBORN COMM. SCH. CORP **Corp ID:** 151600
Address of School Corporation: 6109 Squire Place
City: Aurora **Zip:** 47001 **County Number:** 15
VIN: 4UZAAXCS07CW45100 **License Number:** B751H **Bus Number:** 14
Make of Body: Freightliner **Year:** 2006 **Make of Chassis:** Freightliner **Year:** 2007
Bus Type: C **Mileage:** 127232
Inspection Status: O **Inspected By:** Dan Elmore **PE:** 5960

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.