

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|-------------------------|
| Type of Inspection: | Annual | Date: | 7/27/2020 | Time: | 10:01 AM |
| Name of School Corporation: | SOUTH DEARBORN COMM. SCH. CORP | | | Corp ID: | 151600 |
| Address of School Corporation: | 6109 Squire Place | | | | |
| City: | Aurora | Zip: | 47001 | County Number: | 15 |
| VIN: | 1GB3G2BG6B1170668 | License Number: | G653896 | Bus Number: | 50 |
| Make of Body: | Collins Bus Corporation | Year: | 2011 | Make of Chassis: | Collins Bus Corporation |
| Bus Type: | A2 | Mileage: | 71811 | Year: | 2011 |
| Inspection Status: | O | Inspected By: | Dan Elmore | PE: | 5960 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 64-2-1 | Any rear turn signal does not function properly |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.