REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	7/28/2020	Time:	9:01 AM
Name of Schoo Address of Sch	I Corporation: SC ool Corporation:	OUTH DEARBO 6109 Squire	RN COMM. SCH Place	H. CORP	Corp ID:	151600
City:	Aurora	Zip:	47001		County Number:	15
VIN:	4UZABRDU9ACAN8249)	License Number:	33113	Bus Number:	42
Make of Body:	Thomas Built Buses, Ye Inc.	ar: 2009	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2010
Bus Type:	С		Mileage:	255081		
Inspection Status:	R	Inspected By:	Dan Elmore		PE:	5960

Violations - Rejected

Inspection <u>Code</u>	<u>Description</u>
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.