

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	7/28/2020	Time:	9:15 AM
Name of School Corporation:	LAKE CENTRAL SCHOOL CORP.	Corp ID:	454615		
Address of School Corporation:	8855 Wicker Ave				
City:	St John	Zip:	46373	County Number:	45
VIN:	1GBJG31K191152432	License Number:	80469	Bus Number:	2061
Make of Body:	Collins Bus Corporation	Year:	2009	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	95843		
Inspection Status:	R	Inspected By:	Tim Grayson	PE:	7558

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.