

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	7/29/2020	Time:	9:26 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	1BABKC0A84F216124	License Number:	b775f	Bus Number:	17
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	Blue Bird Corporation
Bus Type:	B	Mileage:	146250	Year:	2004
Inspection Status:	R	Inspected By:	Dan Elmore	PE:	5960

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.