## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 7/29/2020 Time: 8:50 AM

Name of School Corporation: LAKE CENTRAL SCHOOL CORP. Corp ID: 454615

Address of School Corporation: 8855 Wicker Ave

City:St JohnZip:46373County Number:45VIN:4DRBUC8N1JB575451License Number:14337Bus Number:31Make of Body:IC Corporation Year:2016Make of Chassis:IC Corporation Year:2018

Bus Type: C Mileage: 32179

Inspection Status: R Inspected By: Nathan Sherer PE: 7029

## Violations - Rejected

Inspection Code	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.