# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 7/29/2020 | **Time:** | 10:36 AM |
| **Name of School Corporation:** | AUXILIO SERVICES (MUNCIE) | | | | **Corp ID:** | 251807 |
| **Address of School Corporation:** | 11260 Cornell Park Dr Suite 700 | | | | | |
| **City:** | Cincinnati | **Zip:** | 45242 | | **County Number:** | 18 |
| **VIN:** | 1GB3GRBF7H1116451 | | **License Number:** | B889N | **Bus Number:** | M41 |
| **Make of Body:** | Chevrolet **Year:** 2016 | | **Make of Chassis:** | Chevrolet | **Year:** | 2017 |
| **Bus Type:** | A1 | | **Mileage:** | 47801 | | |
| **Inspection Status:** | A | **Inspected By:** | Jamie Hotchkiss | | **PE:** | 6458 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**