

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 8/4/2020 **Time:** 8:23 AM
Name of School Corporation: SOUTH MADISON COMM. SCHOOLS **Corp ID:** 485255
Address of School Corporation: 203 S Heritage Way
City: Pendleton **Zip:** 46064 **County Number:** 48
VIN: 4DRBUSKN2BB327262 **License Number:** 74402 **Bus Number:** 34
Make of Body: IC Corporation **Year:** 2010 **Make of Chassis:** IC Corporation **Year:** 2010
Bus Type: C **Mileage:** 144964
Inspection Status: O **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
22-1-5	See Notes: Any defect inspector deems a violation not listed
33-1-1	The grill has any exposed edges that may cause injury
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely
65-2-1	Warning lights fail to operate correctly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.