

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/20/2020	Time: 8:42 AM
Name of School Corporation: SHERIDAN COMMUNITY SCHOOLS	Corp ID: 293055	
Address of School Corporation: 24795 Hinsley Rd		
City: Sheridan	Zip: 46069	County Number: 29
VIN: 4DRBUSKN0EB403453	License Number: 7615	Bus Number: 7
Make of Body: IC Corporation	Year: 2014	Make of Chassis: IC Corporation
Year: 2014		
Bus Type: C	Mileage: 79542	
Inspection Status: O	Inspected By: Joel Flores	PE: 7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-7	Any emergency window is too difficult to open
50-1-3	The seat belt cutter is contained in a compartment.
50-1-1	The seat belt cutter is not located within the driver's view and reach

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.