

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	8/20/2020	Time:	9:22 AM		
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			Corp ID:	293055		
Address of School Corporation:	24795 Hinsley Rd						
City:	Sheridan	Zip:	46069	County Number:	29		
VIN:	4DRBUC8N0KB101461		License Number:	22180	Bus Number:	9	
Make of Body:	IC Corporation	Year:	18	Make of Chassis:	IC Corporation	Year:	2019
Bus Type:	C			Mileage:	14162		
Inspection Status:	R	Inspected By:	Joel Flores	PE:	7415		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-1	The seat belt cutter is not located within the driver's view and reach
50-1-3	The seat belt cutter is contained in a compartment.
3-1-3	Any battery is loose in its mounting.

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.