REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/20/2020	**Time:**	9:22 AM
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			**Corp ID:**	293055
Address of School Corporation:	24795 Hinsley Rd				
City:	Sheridan	**Zip:**	46069	**County Number:**	29
VIN:	4DRBUC8N0KB101461	**License Number:**	22180	**Bus Number:**	9
Make of Body:	IC Corporation **Year:** 18	**Make of Chassis:**	IC Corporation	**Year:**	2019
Bus Type:	C	**Mileage:**	14162		
Inspection Status:	R	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
50-1-1	The seat belt cutter is not located within the driver's view and reach
50-1-3	The seat belt cutter is contained in a compartment.
3-1-3	Any battery is loose in its mounting.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.