

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/28/2020 Time: 12:23 PM
Name of School Corporation: MILL CREEK COMM. SCHOOL CORP. Corp ID: 323335
Address of School Corporation: 6631 S CR 200 W
City: Clayton Zip: 46118 County Number: 32
VIN: 1GB3GRBG2G1314099 License Number: 123XYZ Bus Number: 16-2
Make of Body: Chevrolet Year: 2016 Make of Chassis: Chevrolet Year: 2016
Bus Type: A1 Mileage: 31679
Inspection Status: R Inspected By: Joel Flores PE: 7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.