REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:8/28/2020 Time:12:23 PMName of School Corporation: MILL CREEK COMM. SCHOOL CORP.Corp ID:323335

Address of School Corporation: 6631 S CR 200 W

City:ClaytonZip:46118County Number:32VIN:1GB3GRBG2G1314099License Number:123XYZBus Number:16-2Make of Body:Chevrolet Year:2016Make of Chassis:Chevrolet Year:2016

Bus Type: A1 Mileage: 31679

Inspection Status: R Inspected By: Joel Flores PE: 7415

Violations - Rejected

Inspection Code	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.