REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/28/2020	**Time:**	12:43 PM
Name of School Corporation:	MILL CREEK COMM. SCHOOL CORP.			**Corp ID:**	323335
Address of School Corporation:	6631 S CR 200 W				
City:	Clayton	**Zip:**	46118	**County Number:**	32
VIN:	1GB3G2BG1F1114899	**License Number:**	32306	**Bus Number:**	15-4
Make of Body:	Chevrolet **Year:** 2015	**Make of Chassis:**	Chevrolet	**Year:**	2015
Bus Type:	A1	**Mileage:**	47195		
Inspection Status:	R	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
57-1-5	Step-well light is missing or inoperative
26-1-4	Not securely mounted
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**