

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/2/2020	Time:	8:18 AM
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS			Corp ID:	475075
Address of School Corporation:	595 Stars Blvd				
City:	Bedford	Zip:	47421	County Number:	47
VIN:	4DRBRAAN94B962947			License Number:	19553
Make of Body:	IC Corporation	Year:	2003	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	83981	Year:	2004
Inspection Status:	R	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.