REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	9/4/2020	**Time:**	1:06 PM
Name of School Corporation:	HAMILTON HEIGHTS SCHOOL CORP.			**Corp ID:**	293025
Address of School Corporation:	PO Box 469				
City:	Arcadia	**Zip:**	46030	**County Number:**	29
VIN:	1GB3G3BG2E1105701	**License Number:**	21562	**Bus Number:**	29
Make of Body:	Chevrolet **Year:** 2014	**Make of Chassis:**	Chevrolet	**Year:**	2014
Bus Type:		**Mileage:**	132575		
Inspection Status:	O	**Inspected By:**	Philip Cooley	**PE:**	8864

Violations - Rejected

Inspection Code	Description
11-1-7	See Notes: Any defect inspector deems a violation not listed
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description