REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	9/8/2020	Time:	11:44 AM
Name of School Address of Scho	•	EASTERN 1037	HANCO 0 E 250			Corp ID:	303145
City:	Charlottesville	Zip:		46117		County Number:	30
VIN:	1BAKGCPA19F26	3848		License Number:	14958	Bus Number:	16
Make of Body:	Blue Bird Corporation	Year: 2009		Make of Chassis:	Blue Bird Corporation	Year:	2009
Bus Type:	С			Mileage:	124217		
Inspection Status:	0	Inspe By:	ected	Jeff Stone		PE:	8184

Violations - Rejected

Inspection Code	<u>Description</u>
66-1-3	See Notes: Any defect inspector deems a violation not listed
48-1-1	Power steering unit leaks at any point
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.