

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 9/10/2020 **Time:** 9:06 AM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL **Corp ID:** 141375
Address of School Corporation: 5494 E SR 58
City: Elnora **Zip:** 47529 **County Number:** 14
VIN: 1FDWE35P55HA51789 **License Number:** 69262 **Bus Number:** ND5
Make of Body: Mid Bus, Inc. **Year:** 2005 **Make of Chassis:** Ford **Year:** 2005
Bus Type: **Mileage:** 78777
Inspection Status: R **Inspected By:** Mike Adams **PE:** 7407

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description