REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	9/16/2020	Time:	9:05 AM
Name of School of Address of School			SDA BAPTI 950 N CR 6	ST CHURCH & S 50 E	SCHOOL	Corp ID:	323318
City:	BROWNSBURG	Zi	ip:	46112		County Number:	32
VIN:	1BAKCCKA96F2340	080		License Number:	B958L	Bus Number:	4
Make of Body:	Blue Bird Corporation	Year: 20	005	Make of Chassis:	Blue Bird Corporation	Year:	2005
Bus Type:	С			Mileage:	56667		
Inspection Status:	0	_	nspected by:	Joel Flores		PE:	7415

Violations - Rejected

<u>Inspection</u> <u>Code</u>	<u>Description</u>
11-1-1	The front bumper does not extend to the edge of the fenders
49-1-2	See Notes: Any defect inspector deems a violation not listed
30-1-3	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative
24-1-5	Any paint is badly faded or peeling
46-1-2	Any seat back or bottom is loose
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
7-1-5	See Notes: Any defect inspector deems a violation not listed
3-1-3	Any battery is loose in its mounting.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half $(\frac{1}{2})$ inch in
20 2 1	diameter.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.