

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	9/17/2020	<b>Time:</b>	11:28 AM
<b>Name of School Corporation:</b>	SOUTH DEARBORN COMM. SCH. CORP			<b>Corp ID:</b>	151600
<b>Address of School Corporation:</b>	6109 Squire Place				
<b>City:</b>	Aurora	<b>Zip:</b>	47001	<b>County Number:</b>	15
<b>VIN:</b>	4UZAAXCS94CM23649	<b>License Number:</b>	B309B	<b>Bus Number:</b>	8
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2003	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	B	<b>Mileage:</b>	226296	<b>Year:</b>	2004
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Chris Clark	<b>PE:</b>	6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
14-1-1	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-2	Any crossmember is rusted sufficiently to weaken floor supports
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**