

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 9/17/2020	Time: 9:17 AM
Name of School Corporation: BETHESDA BAPTIST CHURCH & SCHOOL	Corp ID: 323318	
Address of School Corporation: 7950 N CR 650 E		
City: BROWNSBURG	Zip: 46112	County Number: 32
VIN: 1GDL7T1E82J509458	License Number: B891A	Bus Number: 1
Make of Body: GMC	Year: 2002	Make of Chassis: GMC
Year: 2002	Mileage: 114310	Year: 2002
Bus Type: C		
Inspection Status: O	Inspected By: Jeff Kastenschmidt	PE: 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-7	See Notes: Any defect inspector deems a violation not listed
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
20-1-10	See Notes: Any defect inspector deems a violation not listed
50-1-2	The seat belt cutter is not secured using a positive fastening method.
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-11	There is any defect not in compliance with the minimum school bus brake inspection standards
57-2-1	Any part of the step-well or support structure is rusted through

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.