

## REPORT OF SCHOOL BUS INSPECTION

|                                                           |                                         |                                        |
|-----------------------------------------------------------|-----------------------------------------|----------------------------------------|
| <b>Type of Inspection:</b> Annual                         | <b>Date:</b> 9/22/2020                  | <b>Time:</b> 11:23 AM                  |
| <b>Name of School Corporation:</b> MILLER TRANSPORTATION  | <b>Corp ID:</b> 49022Z                  |                                        |
| <b>Address of School Corporation:</b> 1103 S Tibbs Avenue |                                         |                                        |
| <b>City:</b> Indianapolis                                 | <b>Zip:</b> 46241                       | <b>County Number:</b> 49               |
| <b>VIN:</b> 4DRBUAAP2FB027949                             | <b>License Number:</b> B399L            | <b>Bus Number:</b> 185                 |
| <b>Make of Body:</b> IC Corporation                       | <b>Year:</b> 2013                       | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2015                                         | <b>Mileage:</b> 98326                   | <b>PE:</b> 5805                        |
| <b>Bus Type:</b> C                                        | <b>Inspected By:</b> Jeff Kastenschmidt |                                        |
| <b>Inspection Status:</b> O                               |                                         |                                        |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                     |
|------------------------|------------------------------------------------------------------------|
| 50-1-2                 | The seat belt cutter is not secured using a positive fastening method. |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                  |
|------------------------|-------------------------------------|
| 59-2-4                 | Stop arm does not function properly |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.