

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/23/2020	Time:	10:16 AM
Name of School Corporation:	GOSHEN COMMUNITY SCHOOLS	Corp ID:	202315		
Address of School Corporation:	613 E Purl St				
City:	Goshen	Zip:	46526	County Number:	20
VIN:	1T7Y74D26J1121650	License Number:	14935	Bus Number:	30
Make of Body:	Thomas Built Buses, Inc.	Year:	2016	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:	72643		
Inspection Status:	O	Inspected By:	Wes Rowlander	PE:	7427

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-1	Any door seals are missing, damaged, or torn
52-1-1	There are any loose, broken, or missing mountings
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
25-2-2	Reflective glass is cracked, broken, or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus,

behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.