REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	9/23/2020	**Time:**	10:16 AM
Name of School Corporation:		GOSHEN COMMUNITY SCHOOLS				**Corp ID:**	202315
Address of School Corporation:		613 E Purl St					
City:	Goshen	**Zip:**	46526			**County Number:**	20
VIN:	1T7Y74D26J1121650			**License Number:**	14935	**Bus Number:**	30
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2016	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2018
Bus Type:	D			**Mileage:**	72643		
Inspection Status:	O	**Inspected By:**	Wes Rowlader			**PE:**	7427

Violations - Rejected

Inspection Code	Description
51-1-1	Any door seals are missing, damaged, or torn
52-1-1	There are any loose, broken, or missing mountings
70-1-9	If the words “EMERGENCY EXIT” does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

Inspection Code	Description
51-2-1	The service door does not open or close properly
25-2-2	Reflective glass is cracked, broken, or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.